AG Network

Routine Maintenance at all stations:

- Install 2nd CF Card (in #1 slot) with new firmware and reload configuration file
- Re-center the Trillium if necessary
- Routine battery and solar panel tests
- Check the vault for water?
- Check grade around vault
- Treat equipment enclosure for bugs

- CCAR, Cane Creek
  - Replace Ethernet cable at maintenance shed
  - Do radio check between station and visitors center
  - Once station is back online check from CERI to verify that we have access to router & radios

- FCAR, Ozark Folk Center
  - Install high gain antennas at visitor's center and station
  - Patch door pin holes with Bondo
  - Possible do additional radio testing with popup at station
  - What about a repeater?

- HHAR, Hobbs
  - Steve Horton wants to clear cut the top of the ridge "Damn stations too noisy every time the wind blows it looks like $#&@!" Oops sorry about that. Did the noise test show that?

- LCAR, Lake Charles
  - Patch door pin holes with Bondo
  - See about raising grade around vault
  - Still need Arkansas IT guy to open ports in Firewall to router & radios
  - Replace the router?

- WHAR, Wooly Hollow
  - Patch door pin holes with Bondo
  - See about raising grade around vault

- WLAR, White Oak Lake
  - Try and figure out what the local noise source is.